

- 1. ALL WIRES SHALL BE HMWPE INSULATION, GAUGE PER TABLE OF DETAIL C/1.0.
- 2. CONNECT LEADS IN TEST STATION PER DETAIL C/4.0 AND C/4.0-b. IF MORE THAN TWO PIPELINES ARE BONDED, USE PIPELINE JUNCTION BOX PER STANDARD DETAIL C1.7b.
- 3. RUN ALL WIRES IN 2" PVC SCH40 CONDUIT FROM CONNECTION POINTS UNTIL THEY REACH THE BOTTOM OF TEST STATION ASSEMBLY. ALL WIRES SHALL BE OF SUFFICIENT LENGTH LENGTH TO REACH TERMINAL BOARD WITHOUT SPLICING.
- 4. TYPICAL DETAIL, BONDING OF MORE THAN TWO PIPELINES MAY BE REQUIRED DEPENDING ON PROJECT.
- 5. FOR BONDING OF CROSSING PIPELINES SEE DETAIL C/1.7

WASHINGTON SUBURBAN SANITARY COMMISSION APPROVED: 7-26-21

Make Harmer

Chief Engineer

STANDARD DETAIL

ATTACHMENT OF BONDING WIRES FOR PARALLEL WATER OR METALLIC SEWER PIPELINES C 1.7a